

Visy Pulp and Paper Tumut CEMS - Exceedance Report

14/05/2021

Reporting Period:

1/04/2021 - 1/05/2021

Environment Protection Licence No:

10232

Main Stack 1

Monitoring Location No:

1

Monitoring Type

Continuous

Sample Type:

Air

Description:

Exit point from Stack 1 to atmosphere

Opacity Period: 6 Minutes Limit: 20.00 %						
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
01/04/21 11:00	01/04/21 11:12	Lime Kiln B ESP	Normal (Steady State)	Kiln B ESP tripped due to a high CO spike	Plant stabilized and monitored	51.66
12/04/21 08:42	12/04/21 08:54	Lime Kiln B	Normal (Steady State)	Kiln lost the main flame due to ID fan speed control issues	Adjustments made and plant restarted.	23.68
13/04/21 11:36	13/04/21 11:42	Lime Kiln B	Lime Kiln B Scheduled Start-up/Shut-down	Kiln B off line for buildup shooting causing the Opacity exceedance	Kiln restarted and stabilized	28.52
14/04/21 06:36	14/04/21 06:54	Power Boiler EP	Power Boiler Scheduled Start-up/Shut-down	Power boiler starting up from shut after washing ID fan impeller	Boiler Stabilized	36.31
14/04/21 07:48	14/04/21 08:54	Power Boiler EP	Power Boiler Scheduled Start-up/Shut-down	Power boiler starting up from shut after washing ID fan impeller	Boiler Stabilized	42.17
14/04/21 09:06	14/04/21 09:18	Power Boiler EP	Power Boiler Scheduled Start-up/Shut-down	Power boiler starting up from shut after washing ID fan impeller	Boiler Stabilized	20.55
14/04/21 10:18	14/04/21 10:30	Power Boiler EP	Power Boiler Scheduled Start-up/Shut-down	Power boiler starting up from shut after washing ID fan impeller	Boiler Stabilized	22.09
15/04/21 12:24	15/04/21 12:30	Power Boiler	Power Boiler Un Scheduled Start-up/Shut-down	Power boiler bed sintered again on the 14th and was cleaned	Restarted the boiler on the 15th.	29.21
19/04/21 23:00	19/04/21 23:12	Power Boiler	Power Boiler Un Scheduled Start-up/Shut-down	Vent valve issues boiler running high load.	None.	24.24
21/04/21 02:42	21/04/21 02:48	Lime Kiln B ESP	Normal (Steady State)	Kiln B ESP tripped due to high CO	Plant stabilized	21.33
30/04/21 03:36	30/04/21 04:00	Recovery Boiler A ESP1	Normal (Steady State)	Precip 1 Rotary feeder tripped causing the precip to shut, after restarting the Field 1 tx oil temperature took the field out.	Shearing pin replaced and temperature monitored	90.11
30/04/21 11:06	30/04/21 11:12	Recovery Boiler A ESP1	Normal (Steady State)	Precip field 3 tripped	Field restarted	23.25

30/04/21 15:24	30/04/21 15:42	Recovery Boiler A ESP1	Normal (Steady State)	ESP 1 Shear pin off again causing ESP to trip out	Replaced pin abd restarted ESP	90.15
						-

Sulphur Dioxid	de (SO2)	Period: 60 Minutes	Limit: 250.00 mg/Nm3			
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
13/04/21 10:00	13/04/21 17:00	Power Boiler	Burning NCG/Stripper Gases in Power Boiler	Recovery Boiler A shut down for maintenance and NCG/SOG Diverted to PB	Recovery boiler A restarted and diverted gasses back from PB	342.92

Power Boller

Monitoring Location No:

3

Monitoring Type

Continuous

Sample Type:

Air

Description:

Discharge duct downstream of Power Boiler prior to junction with Stack 1

Carbon Monoxide (CO) Period: 60 Minutes Limit: 140.00 mg/Nm3						
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
01/04/21 15:00	01/04/21 16:00	Power Boiler	Normal (Steady State)	Operational difficulties with process	Working on air systems to find balance, adjust and monitored	157.24
02/04/21 16:00	02/04/21 17:00	Power Boiler	Normal (Steady State)	Operational difficulties with process	Working on air systems to find balance, adjust and monitored	140.27
02/04/21 17:00	02/04/21 18:00	Power Boiler	Normal (Steady State)	Operational difficulties with process	Working on air systems to find balance, adjust and monitored	147.91
04/04/21 15:00	04/04/21 16:00	Power Boiler	Normal (Steady State)	Operational difficulties with process	Working on air systems to find balance, adjust and monitored	198.81
05/04/21 02:00	05/04/21 03:00	Power Boiler	Normal (Steady State)	Operational difficulties with process	Working on air systems to find balance, adjust and monitored	176.51
15/04/21 13:00	15/04/21 17:00	Power Boiler	Power Boiler Un Scheduled Start-up/Shut-down	Power Boiler starting up from a shut caused by sand bed sintering	Plant started and stabilized	250.61
15/04/21 17:00	15/04/21 18:00	Power Boiler	Power Boiler Un Scheduled Start-up/Shut-down	Power Boiler starting up from a shut caused by sand bed sintering	Plant started and stabilized	250.61
20/04/21 05:00	20/04/21 06:00	Power Boiler	Normal (Steady State)	Upset conditions with vent valve stuck open and fuel maximising.	Vent valve manually closed and plant stabilized	153.35

Main Stack 2

Monitoring Location No:

22

Monitoring Type

Continuous

Sample Type:

Air

Description:

Exit point from Stack 2 to atmosphere

Opacity Period: 6 Minutes Limit: 20.00 %						
Start Time	End Time	Cause	Operational State	Explanation	Corrective Action	Max Reading
01/04/21 09:24	01/04/21 09:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	24.6
02/04/21 09:24	02/04/21 09:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	25.7
03/04/21 09:24	03/04/21 09:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	27.0
04/04/21 08:24	04/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	27.2
05/04/21 08:24	05/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	26.4
06/04/21 08:24	06/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	27.3
07/04/21 08:24	07/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	26.4
08/04/21 08:24	08/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	25.0
09/04/21 08:24	09/04/21 08:30	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	20.9
13/04/21 08:18	13/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	21.3
15/04/21 08:18	15/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	22.4
16/04/21 08:18	16/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	22.3
17/04/21 08:18	17/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	22.5
18/04/21 08:18	18/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	22.2
19/04/21 08:18	19/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.4
20/04/21 08:18	20/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	23.6
21/04/21 08:18	21/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.0
22/04/21 08:18	22/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	26.5
23/04/21 08:18	23/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.7
24/04/21 08:18	24/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	26.3
25/04/21 08:18	25/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	27.2
26/04/21 08:18	26/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.7
27/04/21 08:18	27/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	27.9
28/04/21 08:18	28/04/21 08:24	Auto Zero Span Verification	Normal (Steady State)	Auto Calibration	None Required	25.9
29/04/21 08:18	29/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	25.2
30/04/21 08:18	30/04/21 08:24	Recovery Boiler B	Normal (Steady State)	Auto Calibration	None Required	20.4

Authorised By:

Uday Bhagwat Pulp Mill Manager

Johan Stoltz General Manager

Page 4 of 4